



Figure 1: Samples collected by Dept. of Fish and Game (DF&G) during their 25 January 2009 investigation. From left to right, samples are moving from the Property and down Peaslee Creek; the last two samples are from upstream Tuolumne River.



Figure 2: Photo submitted by Lt. McKay. Taken during the DF&G 25 January investigation. Shows sediment discharge from Stanislaus Almond Ranch property; Sample 3 site and significant flow and sediment load past the sediment control structures.



Figure 3: Photo submitted by Lt. McKay. Taken during the DF&G 25 January investigation. Peaslee Creek flowing into the Tuolumne River.